




Clamping Devices

Nuts • Bolts • Washers • Spacer Clamps • Bundle Clamps

Carriage Bolt

| Length | Zinc Plyt. | Stainless |
|--------|------------|------------|
| 1/2" | ZN25CB.50 | SS25CB.50 |
| 3/4" | ZN25CB.75 | SS25CB.75 |
| 1" | ZN25CB1.00 | SS25CB1.00 |
| 1-1/4" | ZN25CB1.25 | SS25CB1.25 |
| 1-1/2" | ZN25CB1.50 | SS25CB1.50 |
| 2" | ZN25CB2.00 | SS25CB2.00 |
| 2-1/2" | ZN25CB2.50 | SS25CB2.50 |
| 3" | ZN25CB3.00 | SS25CB3.00 |



Lock Washers

| Size | Zinc Plyt. | Stainless |
|-----------|------------|-----------|
| 1/4" - 20 | ZN25LW | SS25LW |



Hex Bolt

| Length | Zinc Plyt. | Stainless |
|--------|------------|------------|
| 1/2" | ZN25HB.50 | SS25HB.50 |
| 3/4" | ZN25HB.75 | SS25HB.75 |
| 1" | ZN25HB1.00 | SS25HB1.00 |
| 1-1/4" | ZN25HB1.25 | SS25HB1.25 |
| 1-1/2" | ZN25HB1.50 | SS25HB1.50 |
| 2" | ZN25HB2.00 | SS25HB2.00 |
| 2-1/2" | ZN25HB2.50 | SS25HB2.50 |
| 3" | ZN25HB3.00 | SS25HB3.00 |




Flat Washers

| Size | Zinc Plyt. | Stainless |
|-----------|------------|-----------|
| 1/4" - 20 | ZN25LW | SS25LW |




Wing Nut

| Size | Zinc Plyt. | Stainless | Aluminum |
|---------|------------|-----------|----------|
| 1/4"-20 | ZN25WN | SS25WN | A25WN |



Hex Nut


| Size | Zinc Plyt. | Stainless | Aluminum |
|---------|------------|-----------|----------|
| 1/4"-20 | ZN25HN | SS25HN | A25HN |



Machine Screw & Hex Nut Assembly

Machine screws available in longer lengths

| Size | Zinc Plyt. | Stainless |
|-----------------|------------|-----------|
| 1/4"-20 x 1/2"L | BN-1-ZN | BN-1-ZN |



Spacer Clamps

| | |
|---------------------|---------|
| Two 1/4" O.D. Tubes | PL25SCL |
| Two 3/8" O.D. Tubes | PL37SCL |
| Two 1/2" O.D. Tubes | PL50SCL |



Bundle Clamps

| | |
|---------------|-----------|
| 0 - 1.25" | SS1.25BLC |
| 1.25" - 2.00" | SS2.00BLC |
| 2.00" - 3.00" | SS3.00BLC |
| 3.00" - 4.00" | SS4.00BLC |
| 4.00" - 5.00" | SS5.00BLC |
| 5.00" - 6.00" | SS6.00BLC |

